BUILDING SAFETY CERTIFICATE

No. 40

4.

Dated: 26-06-2023

Certified that the existing building <u>Highland</u> <u>Scholart</u> <u>Scholart</u> <u>(name of the building or premises) at <u>Bleste</u> <u>Bye feats</u> <u>Read</u> <u>Read</u> <u>Readershipsh</u> <u>(Mater Margaren Mater)</u> <u>(Mater Margaren Marga</u></u>

1. Buildiep is in gow Condition till now 2. No crack seemot appear in Buildy Column 3.

* Strike out whichever is not applicable.

25/6/2

Assistant engineer Construction Divi P W D Name :

Designation:

Name & Address of Department/ Office:

(Assistant Engineer & above officer of concerned Govt. Department only)

<u>Note:</u> This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.



1

कार्यालय सहायक अभियन्ता, निर्माण खण्ड, लो०नि०वि०, देहरादून



Office of the Assistant Engineer, Construction Division, P.W.D., Dehradun, Uttarakhand

Website-http://pwd.uk.gov.in

पत्रांक : 40 /

E-mail: eecdpwdddn@rediffmail.com

दिनांक : 26-6 /2023

सुरक्षा प्रमाण पत्र

प्रमाणित किया जाता है कि High Land Scholars School Block ByePass Road Babugarh Vikashnagar District Dehradun का निरीक्षण आपके पत्र दिनांक 23.06.2023 को अपर सहायक अभियन्ता निर्माण खण्ड लोoनिoविo देहरादून द्वारा किया गया तथा पाया गया, कि स्कूल Building के Column एवं छत में कही पर भी Major Cracks नहीं है एवं स्कूल 3 से 4 वर्ष, पुराना है एवं अच्छी हालत में है। स्कूल की संरचना (Structure) प्रथम दृष्ट्या सुरक्षित प्रतीत होती है

ang 26/6/23